

Mine

June 30, 1987

TO: File

FROM: Frank R. Jensen, Reclamation Soils Specialist

*Frank Jensen*

RE: ACT/049/001, Keigley Quarry, USX

On May 11, 1987, the minerals team reviewed the Keigley Quarry with Thon Gin and Roy Benson of USX to help on the permitting of the quarry. A follow-up letter with a recommended seed mixture, etc., was sent to them on June 1, 1987.

Photographs of the quarry for reference purposes follow:



Keigley Quarry, May 11, 1987  
Note the orchards adjoining the quarry.



Page 3  
Memorandum  
DOE/049/001, Keigley Quarry  
June 30, 1987



Keigley Quarry Waste Pile Area, May 11, 1987

The hillside (left of photo) bordering the waste pile has a very good native vegetative cover, including bluebunch wheatgrass, cliffrose, big sagebrush, and rabbitbrush. Vegetation ground cover is approximately 20 percent.

This waste pile area will also need to have topsoil material put on it and properly reseeded to meet revegetation requirements.

clj  
cc: Roy Benson, USX  
1212R/36-38

Page 3  
Memorandum  
DOE/049/001, Keigley Quarry  
June 30, 1987



Keigley Quarry Waste Pile Area, May 11, 1987

The hillside (left of photo) bordering the waste pile has a very good native vegetative cover, including bluebunch wheatgrass, cliffrose, big sagebrush, and rabbitbrush. Vegetation ground cover is approximately 20 percent.

This waste pile area will also need to have topsoil material put on it and properly reseeded to meet revegetation requirements.

clj  
cc: Roy Benson, USX  
1212R/36-38